



Problem Statement:

Develop a solution to troubleshoot and resolve common connectivity errors encountered when interfacing the Atmega328p microcontroller with external sensors and peripherals, ensuring robust and reliable communication. This includes addressing issues such as incorrect wiring, signal interference, and communication protocol mismatches to provide a more user-friendly and efficient development experience for hardware enthusiasts and engineers working with Atmega328p-based projects.

Company name

Onnano Technologies , Karur, Tamil Nadu